Phone: (516) 868-4411
Fax: (516) 868-4609
Website: primelite-mfg.com
Email: sales@primelite-mfg.com

Primelite
MANUFACTURING CORP.
"PROUDLY MADE IN THE USA"

GOOSENECK SIGN LIGHT ASSEMBLY INSTRUCTIONS

1/2" conduit nut
O ring gasket

AMW wire 150 ℃ 60" long

set screw

1/4" - 1/2" cast adapter

1. **Feed the wire from the shade through the gooseneck arm.**
2. **Twist the shade onto the arm's thread at least 3 turns and tighten the set screw.**
3. **Tighten the conduit nut over the arm's threads Be sure to fit the O ring into the groves**

conduit nut

O ring gasket

cast adapter

Completed Assembly

Make sure O ring is in place in cast adapter channel before tightening conduit nut. If done correctly you will barely be able to see the O ring.

set screw

1/2" conduit nut and gasket

gasket for 4" canopy

10/24 x 1/2" stainless screw

4" diameter die cast canopy 1/2" thread

4. **Connect the power box wires with the appropriately-colored accompanying wires provided - green with green, white with white, black with black.**
5. **Wire nuts are not provided.**
6. **Place gasket between the mounting canopy and the junction box.**
7. **Using the 10/24 screws provided, secure the canopy to the junction box. Use all four screws.**